
## **Examples of use**

2




## Increase operating time of the machine spindles with Stark's fast clamp systems





Pallet of draw-in type threejaw chuck with handling grip





Breadboard pallet with flat tension frame



Pressure booster to activate the Stark fast closing clamp cylinder