



Locking controls


Mechanical locking control valves





Further check variations upon request.

11



- 1) SPEEDY
- 2) Pressure switch for clamp signal
- 3) Clamp control valve
- 4) Hydraulic valve for clamp control
- 5) Hydraulic valve to release SPEEDY
- 6) Pressure limiting valve, 40 bar
- 7) Pressure limiting valve, 8 bar
- 8) Lubrication from the machine
- 9) Check valve (bypass)



ines Surface plate with SPEEDY 2000 and clamp control valve.

Clamp control is mandatory for all rotation machines according to DIN-regulations.

01/2007

Shut-off valve




Shut-off vavle for installation in fast closing clamp-plates



Shut-off vavle for installation in fast closing clampplates to shut off individual clamping circuits.

Order no.	Description
804 799	Shut-off vavle
	Key included




- 1) Mark for flow
- 2) Fillister-head screws M4

Control valve with ball valve to piping \emptyset 6/4



Order no.	Description
999 104	Control valve with ball valve to piping





SPEEDY 1000 assembly, 8-fold with pipe system and shut off valve to shut off clamping circuits.